PC220 WIRING DIAGRAM FOR THREE PHASE 3-WIRE STAR OR 3-WIRE DELTA LOAD

UNITS AFTER MAY-1996 ONLY
UNITS BEFORE, REFER TO DOC. No: CD60114E



INPUT	SW1	SW2	SW3	SW4
0-10V	1	0	0	0
0-5V	0	1	0	0
4-20mA	0	0	1	1

"0" - OFF, POSITION CLOSE TO THE EDGE OF THE PCB

'1' - ON, PUSH THE SWITCH TO ON POSITION

FIG. 4

** ONLY 15A & 25A REQUIRE EXTERNAL FUSES

POWERLINK ELECTRONICS LTD.				DESIGNED BY		DATE		CLIENT	TITLE PC220 WIRING DIAGRAM FOR STAR & DELTA LOAD	
				DRAWN BY		DATE	JULY 2002			
				CHECKED BY		DATE				
				APPROVED BY		DATE		PROJECT No:	A3 DRAWING No: CD60114F	R
ISSUE	AMENDMENT	MADE BY	DATE	SCALE:		SHEET :				